




Monthly Report
May-2019



A. Site Energy Production Summary*

	Energy Production (kWh)			
	Site		By Turbine	
	P50 (Expected Production)	Actual Production	W1	W2
May-18	607,000	594,897	296,616	298,281
Jun-18	425,000	410,074	205,521	204,553
Jul-18	385,000	278,804	145,255	133,549
Aug-18	404,000	365,718	185,127	180,591
Sep-18	346,000	399,326	202,515	196,811
Oct-18	649,000	709,011	359,965	349,046
Nov-18	846,000	616,294	307,095	309,199
Dec-18	1,022,000	737,042	376,399	360,643
Jan-19	867,000	942,829	486,578	456,251
Feb-19	908,000	707,729	356,127	351,602
Mar-19	803,000	848,505	435,774	412,731
Apr-19	949,000	852,957	427,080	425,877
May-19	603,000	615,463	306,237	309,226
Production 2019 (ytd) (kWh)	4,130,000	3,967,483	2,011,796	1,955,687
Total Production (kWh)*	8,207,000	7,483,752	3,793,673	3,690,079
Capacity Factor*	28.48%		*Value calculated over the last 12 months	

B. Site Energy Production Graph May-2019



C. Safety Summary

	This Month	Project Cumulative
Recordable Incident(s)	0	0
Near Miss(es)	0	0

D. Planned Maintenance Events**

Date	Event	Duration (hr)	Turbine
June-2019	Goldwind 3.5 Year Maintenance	~8	W1
June-2019	Goldwind 3.5 Year Maintenance	~8	W2

E. Actual Maintenance Events

Date	Event	Planned/Unplanned	Duration (hr)	Turbine
5/2/2019	Snowflake Retrofit	Unplanned	6.76	W1
5/13/2019	Grid Fault	Unplanned	5.50	W1, W2
5/14/2019	Grid Fault	Unplanned	8.36	W1, W2
5/15/2019	Owner/Operator Inspection	Unplanned	4.40	W1
5/28/2019	High Wind Event	Unplanned	6.73	W1, W2
5/31/2019	Goldwind 3.5 Year Maintenance	Planned	5.40	W1

F. Turbine Availability & Downtime

Availability	This Month	Annual To Date
W1	99.87%	99.60%
W2	99.97%	99.21%
Avg	99.92%	99.40%
Downtime (hr)	This Month	Annual To Date
W1	48.95	186.77
W2	35.36	180.88
Total	84.31	367.65

G. Billed Data

Meter Reading (Date/Time)	5/29/2019 12:00 AM
Meter To Date Produced	26,745,169 kWh
Meter To Date Consumed	52,873 kWh
Last Reading Produced	26,123,794 kWh
Last Reading Consumed	52,041 kWh
Billed kWh	620,543 kWh
Next Meter Reading	6/29/2019 12:00 AM

H. Report Notes and Comments

*Change to P50 Expected Production due to Material Change in Circumstance.